


Parallel connection converters:

The output cable thickness needs to be decided to the total output power (Amp).

3 pcs IPC/PB converters:



2 pcs IPC/PB converters

